

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,938,933 B2
APPLICATION NO. : 10/698601
DATED : September 6, 2005
INVENTOR(S) : Starita

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 13, Line 17 "of the damp" should read --of the clamp--;


Column 13, Line 17 "when the damp" should read --when the clamp--;

Column 14, Line 41 "alone" should read --along--; and

Column 14, Line 47 "oboe" should read --pipe--.

Signed and Sealed this

First Day of May, 2007



JON W. DUDAS
Director of the United States Patent and Trademark Office